

FITTING INSTRUCTION

Part Number APH100 Arcadian Retensioning Kit For Henderson Canopy Doors.

WARNING As spring tension could be on the door great care should be taken.

All work is undertaken from within the garage therefore ensure that all tools required are at hand. You may need assistance with step (1).

- 1 Ease the spring tension using the .25" dia toggle bar in the spring clamp at the left hand end of the spring then insert the tension pin in the hole on the spring shaft within the right hand door bracket, ensuring that the pin rests on the top of the bracket support. This removes the tension from the cables.

WARNING: DURING THE NEXT OPERATION GREAT CARE SHOULD BE USED TO ENSURE THAT AT LEAST ONE TOGGLE BAR IS SECURELY LOCATED IN THE SPRING CLAMP AT ALL TIMES.

- 2 With a toggle bar securely located in the spring clamp hole loosen the TWO allen screws with the allen key provided. If there is any tension left on the spring at this stage carefully unwind the spring until all tension is removed. (if you just wish to increase tension a little to balance the door do not remove all the tension on the spring).
- 3 Draw a chalk line along the spring, using the toggle bars wind up the spring by moving each toggle bar in turn in an upwards direction until you have approximately 23 turns(you can count the turns on the chalk line).
- 4 Tighten BOTH socket screws securely and then remove the tension pin. Check that the cables run on the top groove of the cones and that they do not foul the side jamb channels.
- 5 Check that the door operates in a satisfactory manner and readjust the spring tension as required following the above procedure.

ALL WORK IS UNDERTAKEN AT THE OWNERS RISK