

### **FITTING INSTRUCTION**

Part Number APC70 Arcadian Replacement Rollers and Spindles for Cardale Mk11 & 111  
Canopy Doors (Spring Drum Type)

**WARNING** As spring tension is on the door at all times great care must be taken.

All work is undertaken from within the garage so ensure all tools are at hand. You may need assistance with step (1).

- 1 **BEFORE** attempting to change the rollers and spindles you **MUST** lock the tension on the spring drum unit. Using a cloth to protect your hand pull on the cables until the holes in the centre of the spring drum unit line up with the holes in the outer bracket then insert a 6" nail through the holes and gently release the cables. The tension will now be locked and the cables slack.
- 2 Remove the screw at the bottom of the side jamb channel. This allows removal of the cable from the spindle.
- 3 Remove the rollers and spindles and replace with new rollers and spindles. Ensuring that the cables are over the spindles. (see note below)
- 4 Replace the screws in the side jamb channels.
- 5 Make sure the cables are securely fitted into the spring drum unit. Using a cloth to protect your hand pull on the cables and remove the nail then gently allow the cables to return to their position. Ensure that the cables run correctly in the grooves.

**NOTE:** If there is insufficient room between the brickwork and the spindles to remove them, remove the bottom weather strips and ease the bottom of the door into the garage. This will allow sufficient room to remove and replace the rollers and spindles.

**ALL WORK IS UNDERTAKEN AT THE OWNERS RISK**